


# **Portal Monitor for Screening Radiation Victims**

A Thermo-Electron portal monitor is used to rapidly screen radiation victims for radioactive contamination. Below are the various components of the monitor;



## **Portal Monitor Assembly - Components**






PVC Tubing which connects the top of the Vertical Columns and Cables Run Through



Power Cord



Cables
(hook each detector to
Control Unit);
Cables either have BNC or
Phone jack connectors



Foot Plates for Vertical Columns (have wing nuts to attach)

#### **Putting the Portal Monitor Together**

The vertical columns are heavy and recommended that 2 people set the portal monitor up. It's also useful to have a chair or small step ladder to stand on (Note: some facilities have the portal partially/fully set up).


1. Attach Vertical Columns to floor plates (wingnuts/washers on plate). The yellow dots (or letters) on the Vertical Columns must face inside (e.g., towards other column).



2. Determine where you wish to place the Portal Monitor and then place crosspiece on floor to space foot plates.



3. Put the two cables into the crosspiece. Both cables will come out the hole in the elbow of the crosspiece. Note that some of the cables have BNC connectors while newer ones have phone jack connectors.



#### **Detector connector**

4. Connect one end each cable to a Vertical Column while connecting the columns with the crosspiece.





5. Connect the cables coming out of the hole in the crosspiece to the Control Console (for BNC connectors it's on the top of the unit; for phone jacks it's on the bottom).



6. Connect the power cord to Control Console (connector on new units on bottom). The Portal Monitor can also be run on 6 "D" batteries (12 hour run)

Power Cord Connector





7. Power on Portal Monitor. Confirm system starts and runs initial self-test without errors. Both "READY" and "ALARM" lamps will light, a tone will be heard, and the system will perform a 20 second background count. If no errors are found, then a "ready" message will be displayed.



- 8 Perform walk-through test.
  - a) Walk through detector with no source to ensure it does not alarm.
  - b) Place the Cs-137 check source on the yellow circle on each pillar. The unit must alarm when the check source is placed on the circles.
  - c) Slowly walk through the Portal Monitor with a the Cs-137 source located at:
    - 1) Belt level.
    - 2) Head level, and
    - 3) Shoe/ankle level and make sure source alarms.



If the Portal Monitor DOESN'T alarm with the Cs-137 source, the Alarm Sigma may need to be lowered. Conversely, if the monitor seems to alarm without the source present the Alarm Sigma may need to be increased. The complete Field Calibration Procedure is provided on the next page.

#### **General Overview of Portal Monitor**

- 1. Once the monitor is set up, individuals slowly walk through the two pillars (ensure that other victims waiting to be monitored are several feet from the portal monitor).
- 2. If the portal monitor alarms, use a survey meter with a GM probe to determine where contamination is on the victim. In large scale events, the victim may be directed to remove clothing & shower.
- 3. The portal monitor's alarm setting of 1 uCi of Cesium-137 is quite low. The dose rate from a 1 uCi source is 0.33 mrem per hour. To put this into perspective, you would need to be 1 meter away from a 1 uCi Cesium-137 source for 30 hours to receive the same amount of radiation you receive from a typical dental x-ray.
- 4. For health care personnel, the major concern of receiving radiation dose from these patients is from themselves becoming contaminated. Therefore, good contamination procedures must be used when working with these patients.
- 5. An infrared eye ("Occupancy Detector") at the entrance tells the unit to start counting the occupant. If the radiation level above a predetermined alarm level, the unit will audibly alarm. The alarm will stay on until 5 seconds after the alarm condition is cleared (e.g., contaminated individual leaves the portal monitor).
- 6. Portal monitor will constantly monitor background radiation levels & will alarm if background levels become too high. The monitor may need to be powered off/on to determine the new background level or the portal monitor may need to be moved to a lower background area.



# University of Nebraska Medical Center Radiation Health Center

### TSA TPM-903A Portal Monitor

Field Calibration Procedure and Verification Checklist (Reference: Thermo Electron)

| Seria   | d Number:   | Location:   |
|---|---|---|
| Veri fic<br>Perfort   | eose ield Calibration procedure is simple and will en cation Checklist. For users who require a comp mance Verification of the TPM-903A portal m ed. This should be the FEMA recommended lu | lete step by step procedure for performing the<br>onitor, use RHC-IP-22B. A check source is |
| Proce   | edure   |   |
| 1.  | Switch TPM on and ensure that system starts   | up and runs initial self-test without errors.   |
|   | Green lamp OK<br>Red lamp OK<br>Sounder OK<br>No "FAIL" message   |   |
| 2.  | TPM will enter background mode automatica<br>all modes are operational and display shows of<br>counting down from 20. Then a ready message<br>background count.                             |   |
|   | 20 Second countdown OK<br>Ready Message displayed OK  |   |
| <ol> <li>Ensure that the check source is safely placed as far away as possible. total background count-rate. This will be approximately 2000cps in a background environment.</li> </ol> |   |   |
|   | Display counts<br>Note: Should be approximately 200cp   | s per 1uR/hr (normally 2000cps))  |
| 4.  | Perform walk-through tests (Note: Must be re  | peated if any adjustments are made later).  |
|   | A. Without source. Check for no alarm.  | No alarm OK   |
| RHC-II  | P-22A Page 1 o  | f 2 Rev. 1 (10/19)  |

|        | NOTE  | NOTE: If test A fails then go to #8, 4 and set alarm sigma higher by 0.2 sigma.  |   |  |  |
|--------|---|--|---|--|--|
|        | B.  | With check source on head. Check for alarm.  | TPM alarms OK   |  |  |
|        | C.  | With check source on waistline. Check for alarm.   | TPM alarms OK   |  |  |
|        | D.  | With check source on foot, Check for alarm   |   |  |  |
|        | NOTE: If test B, C, or D fails to alarm go to #8, 4 and set alarm sigma lower by 0.2 sigma. |  |   |  |  |
| 5.     |   | "0" to enter password mode then enter "1,2,3,4". "2" for Functions. Press "1" for Show Counts                                  |   |  |  |
|        | A.  | Record background count-rate in each channel with Background Channel #1 Backgr NOTE: Should be 100cps per 1uR/hr approx. (norm | no source present<br>round Channel #2<br>nally 1000cps) |  |  |
|        | В.  | B. Place check source on center of detector #1 and note counts.  Counts for source on Detector #1(Original result)             |   |  |  |
|        |   | (41)   |   |  |  |
|        | C.  | Place check source on center of detector #2 and not  | e counts. Press "#" to exit.                            |  |  |
|        |   | Counts for source on Detector #2(Ori   |   |  |  |
| 6.     | Enter   | 2" for Discriminator Check.  |   |  |  |
| 0.     | Note value of LLD and ULD. Compare with previously noted or factory settings.               |  |   |  |  |
|        | Press "#".  |  |   |  |  |
|        |   | LLD (Factory setting 0.098)  |   |  |  |
|        |   | ULD (Factory setting 5.040)  |   |  |  |
| 7.     | Forton #2.2 for Mariness Charles  |  |   |  |  |
| /.     |   | Enter "3" for Variance Check  Note value of Pass #5 for each detector. This should be less than 0.15.                          |   |  |  |
|        |   | Press "#" to exit.   |   |  |  |
|        | 11033   |  |   |  |  |
|        |   | Variance Channel #1 (Less than 0.15)<br>Variance Channel #2 (Less than 0.15)   |   |  |  |
|        |   |  |   |  |  |
| 8.     | Enter "1" for parameters  |  |   |  |  |
|        |   | note parameter settings and compare with previously  | noted or factory settings.                              |  |  |
|        | A.  | Low alarm and high alarm   |   |  |  |
|        |   | Low Alarm (Factory setting 50  | 100   |  |  |
|        | В.  | High Alarm (Factory setting 50<br>Occupancy hold in  | 100)  |  |  |
|        | Б.  | Occupancy hold in (Factory set   | tting 5)  |  |  |
|        | C.  | Alarm comparison intervals   | ang 5)  |  |  |
|        |   | Alarm comparison intervals (Fe   | actory setting 5)                                       |  |  |
|        | D.  | Alarm Sigma. May be set to a lower value if check  | source fails to alarm the unit.                         |  |  |
|        |   | Alarm sigma (Factory setting 3   |   |  |  |
|        |   | Set to a higher value if too many false alarms occur   | when a source is not present.                           |  |  |
| 9.     | Press   | #" to return to operational mode.  |   |  |  |
| Indivi | dual Pe   | r forming Verification:  | Date:   |  |  |
|        |   |  |   |  |  |